

ALL MAJOR MAKES WHEEL BEARINGS & HUBS



CROSS
REFERENCE
GUIDE

**MAGNETI
MARELLI**

Offered by:
MOPAR

Quality Auto Parts for All Major Makes

Aftermarket Part Number Cross Reference Guide

All-Makes Magneti Marelli Offered by Mopar

Product: Wheel Bearings and Hub Assemblies

For Reference Only. See Application Guide for Actual Vehicle Application and Selection of Correct Part for Vehicle



Magneti Marelli Part Number	Part Attribute (If it drastically affects comparative cost)	OE Part Number	AC Delco Part Number	MOOG Part Number	Raybestos Part Number	SKF Part Number	Timken Part Number
1AMH512000	Hub Assembly	GMC 21011095; GMC 21012556; GMC 7467111; GMC 7467117; GMC 7470603; GMC 7470604;		512000	712000	BR930053	512000
1AMH512001	Hub Assembly	GMC 7466970; GMC 7467108; GMC 7470108; GMC 7470509; GMC 7470523; GMC 7470597; GMC 7470598;	2008	512001	712001	BR930070	512001
1AMH512003	Hub Assembly	GMC 7466992; GMC 7467113; GMC 7467119; GMC 7470519; GMC 7470520; GMC 7470555; GMC 7470556;	2055	512003	712003	BR930074	512003
1AMH512009	Hub Assembly	Toyota 42409-06010; Toyota 42409-06020; Toyota 42409-07020; Toyota 42409-32010; Toyota 42409-33010; Toyota 42409-33020; Toyota 42409-33030; Toyota 42409-33040; Toyota 42410-06010; Toyota 42410-06020; Toyota 42410-33010; Toyota 42410-33020; Toyota 42410-33040;		512009	712009	GRW168	512009
1AMH512012	Hub Assembly	Audi 1J0-501-477A; Audi 1J0-501-477B; Audi 1J0-501-477C; Audi 1J0-501-611; Audi 1J0-501-611A; Audi 1J0-501-611B; Audi 1J0-501-611C; Audi 1J0-598-477; Seat 1J0-598-477; Skoda 1J0-598-477; VW 1J0-501-477A; VW 1J0-501-477B; VW 1J0-501-477C; VW 1J0-501-611; VW 1J0-501-611A; VW 1J0-501-611B; VW 1J0-501-611C; VW 1J0-598-477;		512012	712012	BR930108	512012
1AMH512163	Hub Assembly	Ford 1F1Z-2C299CA; Ford 1F1Z-1104CA; Ford 3F13-2C299CA; Ford 3F1Z-1104CA;		512163	712163	BR930366	512163
1AMH512188	Hub Assembly	Honda 42200-SDA-A51;		512188	712188	BR930383	512188
1AMH512218	Hub Assembly	GMC 88970097; Toyota 42410-01010; Toyota 42410-01020; Toyota 42410-02080; Toyota 42410-12260; Toyota 42410-20190;	RW2063	512218	712218	BR930329	512218
1AMH512285	Hub Assembly	GMC 12413111; GMC 12413112; GMC 12413204; GMC 15798483; GMC 22669735; GMC 22721886; GMC 7467650;	RW2021	512285	712285	BR930430	512285
1AMH512357	Hub Assembly	GM N/A		512357	712357	N/A	512357
1AMH513030	Hub Assembly	Ford F1CZ-1104A; Ford F4CZ-1104C; Ford F7C6-1N069AA; Ford F7CZ-1104AB; Mazda B455-26-15X; Mazda B455-26-15XA; Mazda B455-26-15XB;		513030	713030	BR930043	513030
1AMH513035	Hub Assembly	Honda 42200-S04-005; Honda 42200-S04-008; Honda 42200-S04-028; Honda 42200-SB2-015; Honda 42200-SB2-018; Honda 42200-SB2-025; Honda 42200-SB2-028; Honda 42200-SH3-008; Honda 42200-SH3-018; Honda 42200-SH3-028; Honda 42200-SH3-970; Honda 42200-SR3-005; Honda 42200-SR3-008; Honda 42200-ST3-E01; Honda 42200-SX8-008; Honda 42611-SB2-005; Honda 42611-SB2-025;		513035	713035	BR930033	513035
1AMH513044	Hub Assembly	GMC 7466960; GMC 7466966; GMC 7466967; GMC 7466982; GMC 7466983; GMC 7467140; GMC 7470515; GMC 7470517; GMC 7470518; GMC 7470625; GMC 7470626;	20625	513044	713044	BR930083K	513044
1AMH513061	Hub Assembly	GMC 7466964; GMC 7470012; GMC 7470013; GMC 7470506;	2064	513061	713061	BR930064	513061
1AMH513087	Hub Assembly	GMC 7466976; GMC 7470009; GMC 7470511; GMC 7470512;	2075	513087	713087	BR930076	513087
1AMH513098	Hub Assembly	Honda 44200-S11-018; Honda 44200-SM1-008; Honda 44200-SM1-018; Honda 44200-SM4-000; Honda 44200-SM4-003; Honda 44200-SM4-008; Honda 44200-SM4-013; Honda 44200-SM4-018; Honda 44200-SM4-J00; Honda 44200-SN7-008;		513098	713098	FW156	513098
1AMH513100	Hub Assembly	Ford 3F13-2C3008A; Ford 3F1Z-1104-BA; Ford F50Y-1104A; Ford F8RZ-1104AA; Ford XF12-2C3008B; Ford XF1Z-1104AE; Ford XF1Z1104BA; Ford XF1Z-2C3008B;		513100	713100	BR930179	513100
1AMH513115	Hub Assembly	Ford 1R33-2B633AA1R3; Ford 1R3Z-1104AA; Ford 1R3Z-1104-B; Ford 1R3Z-1104BA; Ford F4CZ-2B663AB; Ford F4CZ-2B663AC; Ford F4ZZ-1104A; Ford F6ZC-2B663AA; Ford F6ZZ-1104AA; Ford F8ZC-2B663AA; Ford F8ZZ-1104AA; Ford YR33-2B663AA; Ford YR33-3C300AA; Ford YR3Z-1104AA; Ford YR3Z-1104BA;		513115	713115	BR930250	513115
1AMH513121	Hub Assembly	GMC 12429204; GMC 7470017; GMC 7470105; GMC 7470143; GMC 7470567; GMC 7470568;	2017	513121	713121	BR930548K	513121
1AMH513124	Hub Assembly	GMC 12413045; GMC 12413046; GMC 7467139; GMC 7470537; GMC 7470607; GMC 7470608;	FW127	513124	713124	BR930097	513124
1AMH513137	Hub Assembly	GMC 12413040; GMC 12413060; GMC 12429201; GMC 12429202; GMC 7470018; GMC 7470561; GMC 7470562; GMC 88957259;	FW153	513137	713137	BR930080	513137
1AMH513179	Hub Assembly	GMC 12413035; GMC 12429203; GMC 12429205; GMC 88964968;	FW128	513179	713179	BR930548K	513179
1AMH513188	Hub Assembly	GMC 12413037; GMC 12413257; GMC 15130858; Isuzu 8-12413037-0; Isuzu 8-15130858-0; Saab 12413037; Saab 12413257; Saab 15130858;	FW121	513188	713188	BR930470	513188
1AMH513203	Hub Assembly	GMC 10334134; GMC 12413005; GMC 12413006; GMC 12413097; GMC 12413098; GMC 12413139; GMC 12413195; GMC 12413196; GMC 12413215; GMC 12413216; GMC 7467505; GMC 7467558; GMC 7467617; GMC 88964096; GMC 89047803;	FW110	513203	713203	BR930184	513203
1AMH513204	Hub Assembly	GMC 12413075; GMC 12413076; GMC 12413164; GMC 22667146; GMC 22701516; GMC 7467575;		513204	713204	BR930316	513204
1AMH513205	Hub Assembly	GMC 12413077; GMC 12413078; GMC 12413165; GMC 22667147; GMC 22701520; GMC 7467576;	FW344	513205	713205	BR930315	513205
1AMH513206	Hub Assembly	GMC 12413197; GMC 12413217; GMC 12413218; GMC 22715554; GMC 7467601;	FW299	513206	713206	BR930433	513206
1AMH513214	Hub Assembly	GMC 12413083; GMC 12413084; GMC 12413166; GMC 12413274; GMC 15799213; GMC 21995732; GMC 22706967; GMC 7467651; GMC 7467687;	FW301	513214	713214	BR930317	513214
1AMH513215	Hub Assembly	GMC 12413087; GMC 12413088; GMC 12413167; GMC 22706425; GMC 7467597;	FW323	513215	713215	BR930314	513215
1AMH515024	Hub Assembly	GMC 15997071; GMC 15997072;	FW125	515024	715024	BR930346	SP550300
1AMH515029	Hub Assembly	Ford 1L34-1104AA; Ford XL3Z-1104AA; Ford YL34-1104AA; Ford YL3Z-1104AA;		515029	715029	BR930423	515029
1AMH515036	Hub Assembly	GMC 10393163; GMC 15102294; GMC 15112382; GMC 15134584; GMC 15233113; GMC 15740291; GMC 15863441; GMC 20804856; GMC 25840785;	FW147	515036	715-36	BR930304	SP550304
1AMH515040	Hub Assembly	Toyota 43502-35210; Toyota 43502-35220; Toyota 43502-60180; Toyota 43570-04010; Toyota 43570-60010; Toyota 43570-60020;		515040	715040	FW194	515040
1AMH515050	Hub Assembly	Ford 1L24-1104AC; Ford 1L24-1104AD; Ford 1L24-1104AE; Ford 1L24-1104AF; Ford 1L24-1104AG; Ford 1L24-1K018AB; Ford 1L2Z-1104AA; Ford 1L2Z-1104AB; Ford 1L2Z-1215AB; Ford 2L24-1104AA; Ford 2L24-1K018AB; Ford 2L2Z-1104AA; Ford 2L2Z-1104AB; Ford 3L24-1K018AA; Ford 3L24-1K018AB; Ford 3L2Z-1104AB; Ford 4L24-1K018AA; Ford 4L2Z-1104AA;		515050	715050	BR930456	515050
1AMH515052	Hub Assembly	Ford 3L24-1104AB; Ford 3L24-1104AC; Ford 3L2Z-1104AA; Mazda 1F80-33-061;		515052	715052	BR930452	515052
1AMH515054	Hub Assembly	GMC 15016169; GMC 15037207; GMC 15052444; GMC 15112380; GMC 15112831; GMC 15233111; GMC 15233112; GMC 15233112; GMC 15772838; GMC 25840784;	FW113	515054	715054	BR930417	515054
1AMH515058	Hub Assembly	GMC 15042868; GMC 15104582; GMC 15112411; GMC 15225770; GMC 15719015; GMC 89059059;	FW166	515058	715058	BR930416	515058
1AMH515071	Hub Assembly	GMC 10393162; GMC 15102293; GMC 15863440;	FW202	515071	715071	N/A	515071
1AMH515079	Hub Assembly	Ford 6L34-2C530AD; Ford 5L34-2C530AE; Ford 5L3Z-1104AA; Ford 5L3Z-1104AB; Ford 6L34-2C530AA; Ford 6L34-2C530DA; Ford 6L3Z-1104AA; Ford 6L3Z-1104DA; Ford 7L34-2B663AB; Ford 7L34-2C530AA; Ford 7L34-2C530AB; Ford 7L3Z-1104A;		515079	715079	BR930460	515079
1AMH515086	Hub Assembly	GMC 15064670; GMC 15104907; GMC 15112408; GMC 15112409; GMC 15115915; GMC 15225750; GMC 15225751; GMC 15753476; GMC 15936732; GMC 89059055; GMC 89059057;	FW164	515086	715086	BR930626	515086
1AMH515096	Hub Assembly	GMC 10393171; GMC 25918329; GMC 25976819;	FW303	515096	715096	BR930661	515096
1AMH515097	Hub Assembly	GMC 10393170; GMC 20883242; GMC 25819677;	FW302	515097	715097	BR930693	515097
1AMH518507	Hub Assembly	GMC N/A; Toyota N/A;		518507	718507	BR930022K	518507
1AMH518508	Hub Assembly	Toyota 43502-32070;		518508	718508	BR930028K	518508
1AMH518509	Hub Assembly	Toyota 43502-06040; Toyota 43502-32070; Toyota 43502-33010; Toyota 43502-33030;		518509	718509	BR930000	518509
1AMH518510	Hub Assembly	Ford 6S4Z-1215A; Ford 7S4Z-1104-A; Ford YS4Z-1104AA;		518510	718510	BR930001	518510
1AMH518514	Hub Assembly	GMC 21011098; GMC 21011953;		518514	718514	BR930166K	518514

Note: Part numbers and applications are subject to change without notice.2

Aftermarket Part Number Cross Reference Guide

All-Makes Magneti Marelli Offered by Mopar

Product: Wheel Bearings and Hub Assemblies

For Reference Only. See Application Guide for Actual Vehicle Application and Selection of Correct Part for Vehicle



Magneti Marelli Part Number	Part Attribute (If it drastically affects comparative cost)	OE Part Number	AC Delco Part Number	MOOG Part Number	Raybestos Part Number	SKF Part Number	Timken Part Number
1AMH518515	Hub Assembly	Ford 4L8Z-1104AA; Ford 6L8Z-1104A; Ford 8L8Z-1104-A; Ford YL8Z-1104AB; Ford YL8Z-1215AA;		518515	718515	BR930200K	518515
1AMH521000	Hub Assembly	Ford 1L24-1109AC; Ford 1L24-1W002AA; Ford 1L2Z-1109AA; Ford 1L2Z-1109AB; Ford 3L24-1W002AA; Ford 3L2Z-1109AA; Ford 6L24-1109-AB; Ford 6L2Z-1109B;		521000	721000	BR930263K	521000
1AMBW00206	Wheel Bearing	Alfa Romeo 1365-16409; Alfa Romeo 2900-60070; Allis-Chalmers 1112001; Allis-Chalmers 214439; Allis-Chalmers 3009115; Allis-Chalmers 30091151; Allis-Chalmers 318729; Allis-Chalmers 4253863; Allis-Chalmers 42538637; Allis-Chalmers 42SMX3; Allis-Chalmers 802379; Allis-Chalmers 9115; Allis-Chalmers Q0008744; AM General 5938677; Aston Martin 119107; Aston Martin 119115; Audi 016311235; Audi 016311235B; Audi 121094806; Auto Union 00625026-40; Auto Union R6206; British Leylands 3A5191; British Leylands 6K656; British Leylands 7H5884; British Leylands 850; British Leylands 9981232; British Leylands JA5191; British Leylands X3203; Bucyrus-Erie 26116650; Bucyrus-Erie RBQ303; Case 01098B; Case 40040; Case A223955; Case XA11746; Caterpillar 165054; Caterpillar 1B3867; Caterpillar 9898; Caterpillar 9B6850; Checker 03290; Citroen 32080; Citroen 88090; Clark 853189; Cockshutt DX074; Cockshutt DXS74; Cockshutt Q31; Cockshutt T9468; Cockshutt Z288C; Cummins 3831; Cummins S16054; Cummins S16071; Daihatsu 053016206; Eaton 25613; Elwell-Parker 6013004; Elwell-Parker 601304; Falk Corp 919670; Fiat 068545; Fiat 071129; Fiat 091740; Fiat 6650; Ford 11528406; Ford 16H7697; Ford 1L24-7025AA; Ford 862066G; Ford 9N715; Ford 9N715B; Ford 9N715C; Ford E0A-7065; Ford E0A-7065A1; Ford E0A-7065A2; Ford E0A-7065A3; Ford E0A-7065A4; Ford E0A-7065A5; Ford E3T2-7025A; Ford GP7719; FWD 205789; FWD 9D3206; GMC 100352; GMC 105388; GMC 108059; GMC 12334391; GMC 12334393; GMC 15581875; GMC 187140; GMC 2939931; GMC 78028; GMC 8351881; GMC 88996664; GMC 903206; GMC 907445; GMC 94027803; GMC 9411249; GMC 954380; GMC 954569; GMC 954570; GMC 954571; GMC 954572; GMC 954645; Goodman 170237; Hyster 43206; International 112028R91; International 238740; International 238740; International 3100294R91; International 3158003R91; International 591691C91; International 610020C91; International 70125C91; International 703980R91; International 703981R91; International 704771R92; International 81900R91; International 81901R91; International 850724C91; International 86276H; International C230; International ST213; International ST213X; International ST213Y; International ST429; Isuzu 9-00006206-0; Isuzu 9-00090121-0; Isuzu 9-00090617-0; Isuzu 9-00090628-0; Jaguar C5687; Jaguar C5867; Jeffrey 104653; Jeffrey 122982; Jeffrey 172638; Jeffrey 97491; John Deere JD7681; John Deere JD8583; Joy 301X1; Joy 321X94; Joy 90371994; Joy 940016206; Joy 94191; Joy 94X206; Joy D94AX206; Joy D94X206; Kenworth 1009; Kenworth KW1009; Kenworth KW1505; Kenworth KW5146; Kia K99606-62063; Lamborghini 008503012; Lee Norse 9007003206; Long 9-90254; Lotus C075R6001; Mack 46AX2; Mack 46AX64; Mack 999GC13015; Massey-Ferguson 1109; Massey-Ferguson 195173M1; Massey-Ferguson AT1040; Massey-Ferguson GA1773; Massey-Ferguson LA1018; Massey-Ferguson S9852; Mazda 9960-66-206; Mazda 9960-66-2063; Mercedes-Benz 0009811525; Mercedes-Benz 3129810525; Mitsubishi MD719320; Mitsubishi MS556006; New Holland 210064; New Holland 29659; New Process (OEM) 15720; New Process (OEM) 68126; New Process (OEM) 68137; Nissan 08062-0601P; Nissan 32133-J2000; Nissan 32405-M5600; Nissan 43210-04100; Opel 720006; Opel 903206; Opel N026560; Opel N26560; Pacamor Kubar 6206; Peugeot 234703; Peugeot 234705; Porsche 113501283; Porsche 113501283A; Renault 7706206; Renault 8022741; Renault 8553100; Rockwell 1428G85; Rover 268126; Saab 703130; Simca 69069P; Studebaker 130262; Studebaker 1542942; Studebaker 1542951; Studebaker 197075; Studebaker 197275; Studebaker 423215; Studebaker 513272; Studebaker 6423213; Studebaker 6423215; Studebaker 661481; Studebaker A57233; Subaru 060162060; Subaru 72303-8070; Suzuki 08113-62060; Suzuki 0926230026; Suzuki 8011362060; Toyota 97100-06206; Triumph 1109; Triumph 1109B5; Triumph 500031; Triumph 513897; Triumph SP75G; Twin Disc M201159; Vauxhall 7124925; Volvo 1014; Volvo 11013; Volvo 35313; Volvo 600083; Volvo 600083; Volvo 6000084; Volvo 684; Volvo 7011013; Volvo 7130; VW 016311235; VW 016311235B; VW 113501283; VW 113501283A; VW 121094806; Wabco 522224; Wabco H2204; Wabco R1534; Wabco R15341; Wabco SF2405; Warner Gear 1000-130-008; Warner Gear X3203AQ; White 1702N2; White 1AP0302; White 22312; White 23212; White 2474T2; White 310525; White 316525; White 332674; White 3547; White 700079; White A13928; White A13930; White A13931; White K206; Yale & Towne 315246; Yale & Towne 500025903; Yale & Towne 5040D1012; Yale & Towne 5045112;	3206	206	6206-J	206WB	
1AMBW05707	Wheel Bearing	Ford 1L24-38A79-AA1L2; Ford 1L24-3A379AA; Ford 1L2Z-3A379AA; Ford 3W1W-1225AA; Ford 3W1Z-1225AA; Ford C7AW-1225A; Ford C7AZ-1225A; Ford E0AZ-1225A; Ford E3T2-3C123B; Ford E3Z2-F7431B; Ford E5S2-1225A; Ford F57Z-3A379AA; GMC 12471606; GMC 3868746; GMC 7451408; GMC 7451595; GMC 7451785; GMC 9428573; Honda 8-07451785-0; Honda 8-09428573-0; Honda 8-97081945-2; Isuzu 8-07451785-0; Isuzu 8-09428573-0; Isuzu 8-97081945-2; Mazda 1F70-26-151; Mazda Z2L1-26-151; Nissan C2319-P9500; Warner Gear 1351-134-001;	RW204	5707		R1563TAV	5707
1AMBW06408	Wheel Bearing	Ford E3TW-1225AA; Ford E3TZ-1225A; Ford E3TZ-1225AA; GMC 7451275; GMC 7451809; GMC 88927028; GMC 94400097; GMC 94400097; John Deere JD8642; Mazda ZL0-26-175; Mazda ZL1-26-175; Mitsubishi 03507898AB; Mitsubishi 3507898AB;	1559TS	6408		R1559TV	6408
1AMBW15101	Wheel Bearing	Allis-Chalmers 0225608; Allis-Chalmers 02256089; Allis-Chalmers 213029; Allis-Chalmers 225608; Allis-Chalmers 519227; Allis-Chalmers 70225608; Austin-Western 312641; Case 11448; Case 40382; Case SW96515; Case W9650; Case W96515; Clark 223210; Clark 223254; Clark 731305; Clark SK20339; Clark SK20379; Clark SK6849; Ford 4C34-1216AA; Ford 4C3Z-1216AA; Ford C8TA-1216A; Ford C8TZ-1216A; Gehl 520032; GMC 14091909; GMC 9437771; GMC 9440715; International 594446R91; International 594585R91; International 820633C91; International AC2253715; John Deere AQX42734; John Deere ATY197A; John Deere JD8190; John Deere XJD16551; Massey-Ferguson 212615M1; Massey-Ferguson 35A9857; New Holland 140869; New Idea K2066; Studebaker 170392; Studebaker 176595; Studebaker 665168; White 25026W; White 52026W; White 865277; White HA5004; White HS5004; White LA5004; White LS5004;	15101	15101		BR15101	15101
1AMBW15245	Wheel Bearing	AL-KO Kober 363916; Allis-Chalmers 0241380; Allis-Chalmers 02413805; Allis-Chalmers 0517381; Allis-Chalmers 0517385; Allis-Chalmers 05173850; Allis-Chalmers 241380; Allis-Chalmers 3015581; Allis-Chalmers 30155816; Allis-Chalmers 517381; Allis-Chalmers 624417; Allis-Chalmers 624427; Allis-Chalmers 70241380; Allis-Chalmers 715076; Allis-Chalmers AMX13375; AMC 171172; AMC 171846; AMC 171911; AMC 204635; AMC 3112540; AMC 3119916; AMC 3124570; AMC 3129314; AMC 711481; AMC 71846; AMC 803054; AMC 804054; AMC F171846; AMC J3124570; Case W10153; Caterpillar 15525; Caterpillar 3D7113; Caterpillar A15525; Clark 654162; Deutz-Allis 0241380-5; Dexter Axle 031-029-01; Eaton 656274; Ford 8A-1202; Ford 8A-1202A; Ford C8TA-1217A; Ford C8TZ 1217-A; Gehl 520033; Gerlinger A15525; GMC 455221; GMC 9412869; GMC 9412872; GMC 9437771; Goodman 2150070; Great Plains 28966; Hayes 093725; International 176082H1; International 520942R1; International 520946R1; International 59182M0C1; International 594163R1; International 642954R1; Jeffrey 62713; John Deere JD7449; John Deere JDX73763; John Deere JDX89920; John Deere JDX92441; John Deere M1082T; John Deere TY12332; Joy 9600791; Joy 96X15245; Kenworth KW1221; Kenworth KW3050; Mack 823615245; Massey-Ferguson 195182M1; Massey-Ferguson 763402M1; Massey-Ferguson 59838; New Holland 28966; New Idea K2283; Studebaker 419701; Studebaker 677309; Towmotor A15525; Toyota 97700-15245; Volvo 181131; Volvo 181308; Volvo 181458; Wabco 2150070; White 10A0693; White 125X41; White 50310; White 5M0310; White 82M27; White 895425L; White C514454; White EX78; White LB5004; White LB5013; White TG9503;	15245	15245		BR15245	15245
1AMBW25877	Wheel Bearing	Allis-Chalmers 0228509; Allis-Chalmers 02285096; Allis-Chalmers 043933; Allis-Chalmers 228509; Allis-Chalmers 70228509; Allis-Chalmers 78010078; Allis-Chalmers 8010078; Allis-Chalmers AMX20008; Allis-Chalmers X38422;		25877		BR25877	25877
1AMB510006	Wheel Bearing	Toyota 90080-36021; Toyota 90080-36021-D; Toyota 90080-36078; Toyota 90369-43008; Toyota 90369-43009;		510006	710006	FW153	510006

Note: Part numbers and applications are subject to change without notice.3

Aftermarket Part Number Cross Reference Guide

All-Makes Magneti Marelli Offered by Mopar

Product: Wheel Bearings and Hub Assemblies

For Reference Only. See Application Guide for Actual Vehicle Application and Selection of Correct Part for Vehicle



Magneti Marelli Part Number	Part Attribute (If it drastically affects comparative cost)	OE Part Number	AC Delco Part Number	MOOG Part Number	Raybestos Part Number	SKF Part Number	Timken Part Number
1AMB510030	Wheel Bearing	Honda 44300-S04-A01; Honda 44300-S04-A02; Honda 44300-S5A-000; Honda 44300-S5A-004; Honda 44300-S5A-008; Honda 44300-S6D-E01; Honda 44300-SD6-E01; Honda 44300-SR3-A02; Honda 44300-SR3-A04; Honda 44300-ST3-E01; Rover GHK1559;		510030	710030	FW171	510030
1AMB510050	Wheel Bearing	Honda 42200-S3V-A01; Honda 44300-S0A-003; Honda 44300-S1A-E01; Honda 44300-S47-008; Honda 44300-S84-A01; Honda 44300-S84-A02; Honda 44300-SCA-E01;		510050	710050	FW45	510050
1AMB510063	Wheel Bearing	Ford 7T41-1215BA; Ford 7T42-1215B; GMC 19184284; Mazda GP9A-33-047; Mazda GP9A-33-047A; Toyota 90080-36193; Toyota 90363-A0001; Toyota 90369-15004; Toyota 90369-45003; Toyota 90369-45004; Toyota 90369-45005;		510063	710063	FW50	510063
1AMB510070	Wheel Bearing	GMC 88970116; GMC 88971027; Toyota 90080-36087; Toyota 90080-36136; Toyota 90363-40066; Toyota 90363-40067; Toyota 90363-40067-00; Toyota 90363-40069;	FW137	510070	710070	FW188	510070
1AMB513058	Wheel Bearing	Ford E6DC-1215AA; Ford E6DZ-1215A; Ford E9DC-1215AA; Ford E9DZ-1215A; Ford F1DC-1215AA; Ford F1SZ-1215A; Hyundai 51720-2J000; Hyundai 51720-2J100; Hyundai 51720-FL047; Hyundai 52710-26500; Hyundai 52710-26510; Hyundai 52710-26530; Jaguar MJA1830AD; Jaguar MJA1830AE; Kia OK552-33-047; Kia OK56A-33-047; Kia OK56B-33-047; Kia 50310-3E101; Kia 50310-3E102; Kia 50310-3E200; Kia 51720-2J000; Kia 51720-2J100; Kia 51720-FL047; Kia 52710-26500; Kia 52710-26510; Kia 52710-26530;		513058	713058	FW115	513058
1AMB513067	Wheel Bearing	AAM 74008157; GMC 12479031; GMC 9442126; Isuzu 8-12479031-0; Saab 12479031;	DK59047	513067	713067	DK59047	513067
1AMB517011	Wheel Bearing	Toyota 90080-36071; Toyota 90369-54001; Toyota 90369-54002;		517011	717011	FW189	517011
1AMBW0382A	Wheel Bearing	AAM 74006881; Allis-Chalmers 0212037; Allis-Chalmers 0212037G; Allis-Chalmers 10578; Allis-Chalmers 212037; Allis-Chalmers 3010578; Allis-Chalmers 30105787; Allis-Chalmers 70212037; Allis-Chalmers 73010578; Allis-Chalmers X48313; AMC 919661; AMC 943660; Austin-Western 313037; Case 40467; Case X303A215; Case XA43233; Caterpillar 54835; Caterpillar 7H4566; Caterpillar 7H4566T; Caterpillar 954413; Clark 223222; Clark 658998; Clark G223284; Clark SK20327; Cockshutt T9424; Eaton 20641; Eaton 322478; Eaton 545905; Eaton 723873E; Ford C5NNA768A; Ford C5NNP777A; Ford TCAA-1243A; FWD 9A382A; Gallon D44932A; Gallon D62599; Gehl 520013; Gerlinger A629827; GMC 09436881; GMC 142223; GMC 7451691; GMC 7451693; GMC 7451928; GMC 9422481; GMC 9436881; GMC D51285; GMC TB6326; Goodman 2150007; Goodman 3950457; Hyster 45733; International 105497H; International 105504H; International 158237C91; International 167717C1; International 167720C91; International 187545R91; International 207234H1; International 3044444R91; International 327194R91; International 384350R1; International 388533R1; International 392689R1; International 402353R91; International 591674C1; International 613861C91; International 675709R91; International 826925C1; International 890132H1; International 984363C1; Jeffrey 150804; Jeffrey 150805; Jeffrey 62908; John Deere JD7425; John Deere JD8013; John Deere JDX49202; John Deere OX35076; Joy 9600172; Joy 96X382A; Kaiser-Frazer 943660; Kenworth KW1583; Mack 149505; Mack 64AX148;	387AS382A	382A		382A	382A
		Massey-Ferguson 195521M1; Massey-Ferguson 195525M1; Massey-Ferguson 196068M1; Massey-Ferguson RX2903; Mercedes-Benz 0009800702; Mercedes-Benz 0009813580K2; Mercedes-Benz 0009814581KZ; Mercedes-Benz 0019812505; Mercedes-Benz 0029801702; New Holland 49029; Studebaker 664736; Versatile 84816; Wabco 2150007; Wabco 471489; Wabco VX3437; White 107845A; White 10A7292; White 158381A; White 1AE033A; White 35475; White 516149E; White 7AB5003; White 7XA315; White 90162; White CBX2011; White EX6431; White HSX864; White HSX865; White RT8109A; White RT9009A; White TM3278;					
1AMBW0387A	Wheel Bearing	Allis-Chalmers 0211169; Allis-Chalmers 02111698; Allis-Chalmers 211169; Allis-Chalmers 70098317; Allis-Chalmers 70211169; AMC 918400; Austin-Western 312065; Austin-Western 634376; Brockway 149651; Caterpillar 54834; Caterpillar 855857; Checker O3582; Clark 648334; Eaton 651247; Ford B5D-4221A; Ford B5Y-4242A; Ford GBT307781; Ford TBAF-4221A; Ford TCAA-1244; Ford TCAA-1244A; Gallon D70626; Gehl 520014; GMC 455501; GMC 5269648; GMC 7451692; GMC 9412406; GMC 9412408; Goodman 2140009; Hyster 78584; International 164863H1; International 591801C91; International 659458R91; International 659461R91; International 659714R91; International 890109H1; Jeffrey 150806; John Deere 49X50002A; John Deere JD8161; Mack 62AX285; Massey-Ferguson 835151M1; Massey-Ferguson ET38515; New Holland 166258; Studebaker 640080; Towmotor A54834; Versatile 52151; Volvo 18500; Wabco 2140009; Wabco 471490; White 137D5; White 26804W; White 341119; White 35A4161;	387A	387A		387A	387A
1AMBW387AS	Wheel Bearing	Allis-Chalmers 0218285; Allis-Chalmers 02182855; Allis-Chalmers 218285; Allis-Chalmers 70218285; Austin-Western 319014; Ford C5NNA767A; Ford C7T2-1244A; Ford F81A-1244BA; Ford F81Z-1244BA; Gerlinger A629826; GMC 9436882; International 327195R91; International 613862C91; International 826926C91; John Deere 49X50209A; John Deere JD8147; Joy 9500172; Joy 95X387AS; Massey-Ferguson 206087M1; New Holland 49030; Wabco 181-267; White 10X15157;		387AS		387AS	387AS
1AMBW0010A	Wheel Bearing	AM General 5597027; AM General 5997027; AM General 994262; AM General SB-994262; GMC 7451960; GMC 9428063; Hyundai 52701-43310; Hyundai 52701-43320; International 394730C91; Jeep 83503064; Kia OK72A-26-151; Nissan 40210-75210; Suzuki 43591-82200;	S10	A10		BR10	SET10
1AMBW0012A	Wheel Bearing	BMW 31-21-1-106-032; BMW 31-21-1-119-571; BMW 31-21-1-468-884; BMW 31-21-9-061-512; British Leylands C-45710; Ford D0AA-1215A; Ford D0AZ-1216A; Ford D0AZ-1217B; Ford F65Z-1216AA; Ford XD0AA-1215I; GMC 9439955; Jaguar C045710; Jaguar C45710; Mercedes-Benz 0009809302; Mercedes-Benz 0029802002; Mercedes-Benz 0029806502; Mercedes-Benz 1293300151; Mercedes-Benz 1293300351; Mercedes-Benz 1293300525; Mercedes-Benz 2023300051; Mercedes-Benz 2033300051; Mercedes-Benz 2103300051; Mercedes-Benz 2103300325; Toyota 90368-22001; Toyota 97770-12749; VW 251-405-645B; VW 281-498-625;	S12	A12		BR12	SET12
1AMBW0016A	Wheel Bearing	Ford 90WT-4220A1A; Ford 96WT-4220AA; Ford 96WZ-4220AA; Ford E3FZ-7F431A; Ford YS4Z-4221AA; GMC 12523059; GMC 12523286; GMC 88894092; GMC 88894093; GMC 9439958; International 536055R91; Joy 543308-7; Porsche 999-059-060-00; Porsche 99905906700; Toyota 90368-21082; Toyota 97770-12711; Volvo 184074; Volvo 271391; Volvo 271391-5; Volvo 271392; Volvo 271392-3; Volvo 271703; Volvo 271703-1; Volvo 273824;	S16	A16		BR16	SET16
1AMBW0017A	Wheel Bearing	AL-KO Kober K363192; British Leylands RTC1347; Chrysler 3683975; Chrysler 3838045; Chrysler 5097737A; Chrysler 5252823; Dexter Axle K71-390-00; Ford E7GZ-4221A; Ford E8BZ-4221A; Ford F3CZ-7G023A; Ford F4BZ-4221B; Ford FU601-96A0; Ford XW32034; GMC 9440463; International 536052R91; International 538490R91; Jaguar CAC004999; Jaguar CAC4999; Joy 543308-4; Kia OF001-27-350; Kia OK001-27-350; Mazda F001-27-305; Mazda F001-27-350; Mercedes-Benz 0019803002; Mercedes-Benz 0029801902; Mercedes-Benz 1293300051; Porsche 999.059.059.00; Porsche 999-059-061-00; Rover RTC1347; Rover RTC1347; Toyota 90368-34083; Vauxhall 9966510; Volvo 183576; Volvo 183578; VW 095-321-851;	S17	A17		BR17	SET17
1AMBW0018A	Wheel Bearing	AAM 74006759; Daewoo 96108125; Ford D4AA-1200AA; Ford E7GZ-1216B; Ford F4BZ-1215A; Ford F65Z-1201AA; GMC 26046759; GMC 26046795; GMC 9437733; GMC 96108125; GMC 96335754; Hyundai 51720-FD000; International 61803C91; Isuzu 8-26046759-0; Kewanee Machine B2373; Kia OK01A-33-075; Kia OK211-27-350A; Kia OK211-33-075; Kia 51720-FD000; Kia KK150-33-047; Mazda B001-33-047; Mazda FB01-33-047; Mazda S231-33-075; Opel 370016; Opel 90142867; Peugeot 3125.19; Saab 26046759; Suzuki 09265-38001; Toyota 90368-38001;	S11	A18		BR11	SET11

Aftermarket Part Number Cross Reference Guide

All-Makes Magneti Marelli Offered by Mopar

Product: Wheel Bearings and Hub Assemblies

For Reference Only. See Application Guide for Actual Vehicle Application and Selection of Correct Part for Vehicle



Magneti Marelli Part Number	Part Attribute (If it drastically affects comparative cost)	OE Part Number	AC Delco Part Number	MOOG Part Number	Raybestos Part Number	SKF Part Number	Timken Part Number
1AMBW0002A	Wheel Bearing	Alfa Romeo 11600.21048.01; Alfa Romeo 11900.21408.00; Alfa Romeo 60523333; Alfa Romeo 60747299; Allis-Chalmers EX23051; Aston Martin 690054; Audi 006-311-427A; Audi 211-405-645B; Audi 211-405-645D; Audi 443-505-509; Audi 684-290-987; BMW 2634103; BMW 31-21-1 468-888; BMW 31-21-1-107-456; BMW 31-21-1-634-103; BMW 31-21-2-634-103; BMW 31-21-2-634-107; BMW 31-24-2-634-103; British Leylands 129897; British Leylands 524157; British Leylands ATA4238; British Leylands C15352; British Leylands GHB102; Bucyrus-Erie 2678464-9M; Case A23174; Daihatsu 90368-19037-000; Eaton 305691; Fiat 4096104; Ford 204E-1215; Ford 204E-1215A; Ford 204E-1215A1; Ford 204E-1215A2; Ford 3992410; Ford 81AB-1238AA; Ford 8A-1215C; Ford DORY-1216A; Ford D5NN-1215A; Ford E0ZZ-77F431A; Ford E3TZ-1215A; Ford E7GZ-1216A; GMC 11055109; GMC 457478; GMC 7413409; GMC 7450627; GMC 9440445; Honda 91052-671-000; Honda 91052-671-0000; Honda 91052-671-004; Honda 91052-671-008; Honda 91052-671-0080; Honda 91066-504-8100; Hyundai 52730-36200; International 202502C91; International 202514C91; International 594876R91; International 651816R91; International 652072R91; International 652078R91; International 804853R91; International 827471C91; International FSK6151; Isuzu 5-09812009-0; Isuzu 9-00093067-0; Jaguar 8L03030; Jaguar C15352; John Deere XJD26039; Kia 00317-33-075; Lada 2101-3103025; Lee Norse 501173; Lotus 36C6041; Massey-Ferguson 1851799M91; Massey-Ferguson 647777M91; Mazda 0313-30-075; Mazda 0317-33-075; Mazda 8501-33-047; Mazda B092-26-075; Mazda Z2L0-33-047; Mercedes-Benz 0009815905; Mercedes-Benz 0019810905KZ; Mercedes-Benz 1073300051; Mercedes-Benz 1113300051; Mercedes-Benz 1115860433; Mercedes-Benz 1153300051; Mercedes-Benz 1155860333; Mercedes-Benz 2013300251; Mercedes-Benz 431571; Mitsubishi MB002073; Mitsubishi MB515027; Nissan 40125-A0100; Nissan 40215-A0100; Nissan 40215-Y9500; Nissan 43215-A0100; Opel 330012; Opel N055100; Opel N055101; Porsche 999.059.007.00; Porsche 999.059.009.00; Porsche 999.059.013.00; Porsche 999.059.065.00; Seat FA15824400; Simca 471096; Simca 66177V; Toyota 90368-19037; Toyota 90368-19037-77; Toyota 90368-19037-85; Triumph 129897; Volvo 181586; VW 006311427A; VW 211405645; VW 2114056450; VW 211405645B; VW 211405645D; VW 443-505-509; White 102719A; Yale & Towne 305691;	S2	A2		BR2	SET2
1AMBW0003A	Wheel Bearing	British Leylands 37H8136; British Leylands 607199; Caterpillar 4R3176; Caterpillar J4X7958; Fiat 4096591; Ford 3992409; Ford C1VV-1215A; Ford CIVV-1215A; Ford CLVV-1215A; Ford E8BZ-7025B; Ford F4BZ-7025B; Ford LF-1215A; GMC 457049; GMC 7450697; Hyundai 51703-44030; International 371881R91; International 371906R91; International 458926R91; International 56500C91; International 596565R91; International 671080R91; Isuzu 8-94242913-0; Isuzu 8-94242914-0; Isuzu 8-94361801-0; Mazda B501-17-190A; Mercedes-Benz 0009816305; Mercedes-Benz 1163300051; Mercedes-Benz 1165860033; Mercedes-Benz 1263300051; Mercedes-Benz 6113300725; Mitsubishi MB109565; Mitsubishi MB633087; Nissan 40215-92400; Nissan 40215-F1700; Nissan 40215-F1700TM; Nissan D0215-F1700; Porsche 99905908900; Porsche 99905908901; Saab 8701906; Toyota 04421-35020; Toyota 90368-21001; Toyota 90368-21011; Toyota 90368-21065; Vauxhall 8824117; White 4028995S; White AP3652;	S3	A3		BR3	SET3
1AMBW0034A	Wheel Bearing	GMC 14045734; GMC 14066918; Isuzu 8-14066918-0;	S34	A34		BR34	SET34
1AMBW0035A	Wheel Bearing	Alfa Romeo 10564.17211.00; Alfa Romeo 60506908; AM General 925446; AM General 58-925446; Audi 012-409-123; Audi 016-409-123; Audi 016-409-123B; Audi 016-409-399; Audi 018-409-123; Audi 01E-409-123; Audi 088-409-123; BMW 33-131-205-124; BMW 33-131-213-892; BMW 33-133-205-124; BMW 3604150; British Leylands 522190; British Leylands ATJ2022; British Leylands BTB9000; British Leylands GHB142; Caterpillar 1P9341; Ford 3992412; Ford E1FZ-4221A; Ford E1FZ-4221B; Ford E3FZ-4221A; Ford WAA-4220A; Ford XW185; GMC 12350936; GMC 457232; GMC 7451226; GMC 93334162; Honda 9-00093074-0; Hyundai 43329-37040; Hyundai 53521-44010; International 144081C91; International 202520C91; International 3142104R91; International 3221284R91; International 598756R91; International 627706C91; International 627746C91; International 627748C91; International 663556R91; International 665097R91; International 671074R91; Isuzu 5-09812024-0; Isuzu 9-00093074-0; Jaguar CAC6332; Jaguar JLM21053; Jaguar MNC3280AA; John Deere AQX52292; Kia 43329-37040; Mazda 8501-27-305; Mercedes-Benz 001 980 62 02; Mercedes-Benz 001 980 63 02; Mercedes-Benz 001 981 62 02; Mercedes-Benz 001 981 63 02; Mercedes-Benz 608 981 00 05; Mercedes-Benz 688 981 70 05; Mitsubishi MB092151; Nissan 40215-C6000; Nissan 40215-WB060; Opel T5570; Porsche 012-409-123; Porsche 922.302.155.00; Rover 522190; Rover RTC2726; Saab 8704389; Simca 32391; Toyota 90368-41001; Toyota 90368-41003; Toyota 90368-41004; Toyota 90368-41050; Toyota 90368-41053; Toyota 90368-41056; Toyota 90369-41050; Volvo 183510; Volvo 183510-7; VW 012-409-123; VW 016-409-123; VW 016-409-123B; VW 016-409-399; VW 018-409-123; VW 01E-409-123; VW 088-409-123; VW 2234; White 102729A;	S45	A35		BR35	SET45
1AMBW0037A	Wheel Bearing	Alfa Romeo 11900.17211.01; Aston Martin 68-26-0014; Audi 005-404-123; Audi 005-409-123; Audi 005-409-551A; Austin-Western 301SE630; British Leylands 606334; British Leylands ATJ2063; British Leylands GHB197; Brockway 149519; Brockway 149602; Caterpillar 6X1027; Ford E43Z-4221A; Ford WAC-4220; Ford WAC-4220A; Ford XW293; GMC 457235; GMC 7451090; GMC D54912; International 144072C91; International 200707H1; International 371909R91; International 452478C91; International 619385R91; International 69547C91; Isuzu 1-09812016-0; Isuzu 9-00093160-0; Isuzu 9-00093165-0; John Deere AQX65055; Joy 543308-3; Mazda Z2L0-27-307A; Mazda Z2L1-27-305; Mazda Z2L1-27-305A; Nissan 40210-0F000; Nissan 40210-25600; Nissan 40210-50W00; Nissan 40210-50W10; Opel B25; Peugeot 312509; Porsche 999.059.008.00; Porsche 999.059.011.00; Rover RTC3429; Rover STC4382; Twin Disc M2362; Twin Disc M2362A; VW 005-404-123; VW 005-409-123; VW 005-409-551A; White 107848A;	S37	A37		BR37	SET37
1AMBW0038A	Wheel Bearing	GMC 7451812; GMC 9428908; International 364464C91; International 431669C91; Mack 46AX90;	S38	A38		BR38	SET38
1AMBW0004A	Wheel Bearing	Alfa Romeo 11600.21413.00; Alfa Romeo 60724054; AL-KO Kober K336180; Audi 311-405-615; Audi 311-405-625; Audi 803-501-283; BMW 2634105; BMW 31-21-2-634-105; British Leylands 132066; British Leylands BTB594; British Leylands GHB101; British Leylands UKCO133; DAF 70523997; Daihatsu 90368-23027; Daihatsu 90368-26027; Dexter Axle K71-306-00; Eaton 648563; Ford 11527973; Ford 3024E-1200A; Ford 3024E-1200A1; Ford 59721; Ford CDD-1200A; Ford CDD-1200; Ford D8RZ-1225A; Ford E8BZ-1244A; Ford F4BZ-1215B; GMC 054470; GMC 7451080; GMC 7451369; GMC 90490861; GMC 90511065; GMC 94115132; GMC 9415132; Hyundai 51720-11000; Hyundai 51720-11101; Hyundai 52710-FD000; International 3142105R91; International 572562R91; International 583971R91; International 815800C91; International 827468C91; Isuzu 8-94201309-0; Isuzu 9-00093605-0; Isuzu 9-00093606-0; Isuzu 9-00093606-1; John Deere AQX64575; Kia 52710-FD000; Kia KKY01-33-047; Kia MB002-33-047; Lotus 36C6042; Mazda 8002-33-047; Mazda F401-17-190; Mitsubishi A125842; Mitsubishi MA125842; Mitsubishi MB001835; Mitsubishi MB125842; Mitsubishi MB515921; Nissan 40210-21000; Nissan 40210-A0800; Nissan 43210-01800; Opel 328017; Opel 94024130; Opel N054470; Rolls-Royce UG12175; Rolls-Royce UG13545; Saab 810624; Saab 8719163; Saab 890624; Simca 20339D; Simca 543812; Talbot 20339D; Toyota 90365-25002C; Toyota 90368-26013; Toyota 90368-26013-85; Toyota 90368-26013A; Toyota 90368-26027; Toyota 90368-26027-85; Triumph 132066; Vauxhall 11054479; Vauxhall 6368762; Volvo 183834; Volvo 183834-1; VW 311-405-615; VW 311-405-625;	S4	A4		BR4	SET4

Note: Part numbers and applications are subject to change without notice.5

Aftermarket Part Number Cross Reference Guide

All-Makes Magneti Marelli Offered by Mopar

Product: Wheel Bearings and Hub Assemblies

For Reference Only. See Application Guide for Actual Vehicle Application and Selection of Correct Part for Vehicle



Magneti Marelli Part Number	Part Attribute (If it drastically affects comparative cost)	OE Part Number	AC Delco Part Number	MOOG Part Number	Raybestos Part Number	SKF Part Number	Timken Part Number	
1AMBW0005A	Wheel Bearing	Aston Martin 4HU025-1; Audi 008-311-123; British Leylands 13H458; British Leylands 606472; British Leylands 88G273; British Leylands GHB144; Case 40037; Daihatsu 90368-34020; Euclid E551730; Fiat 4096587; Ford 310114; Ford CODW-4220A; Ford COWD-4220; Ford CLVW-1200A; Ford D12W-4220A; Ford E02Z-7025A; Ford F4Z2-7025A; FWD 93332; GMC 12523054; GMC 457052; GMC 7450700; GMC 7451728; GMC 9301151; GMC 94249619; GMC E551730; Hyundai 51701-44000; Hyundai 51701-44030; International 144075C91; International 202505C91; International 202517C91; International 3043871R91; International 3048A1C17; International 3142106R91; International 371896R91; International 56503C91; International 618022R91; International 671077R91; Isuzu 8-94242683-0; Isuzu 8-94242916-0; Isuzu 8-94249619-0; Isuzu 8-94249619-3; Isuzu 8-94361804-0; Isuzu 8-97028080-0; Isuzu 9-00093101-0; Isuzu 9-00093124-1; Jaguar 11101; Jaguar 4HU0251; Kewanee Machine X5655; Kia 05083-33-047; Massey-Ferguson 1851800M91; Mazda S083-33-047; Mazda UE54-33-047; Mazda UE54-33-042; Mazda ZZM0-33-075; Mercedes-Benz 0009816405; Mercedes-Benz 0019802902; Mercedes-Benz 0069815105; Mitsubishi A141043; Mitsubishi MA141043; Mitsubishi MB109564; Mitsubishi MB633086; Mitsubishi MQ902158; Nissan 40210-92400; Nissan 40210-F1700; Nissan 40210-HC000; Nissan D0210-F1700; Rockwell XC318903; Toyota 34020; Toyota 90368-34001; Toyota 90368-34020; Toyota 90368-34039; Toyota 90368-34040; Vauxhall 7170351; Volvo 184083; Volvo 273872; Volvo 273872-2; VW 008311123; VW 361501283A;	S5	A5			BR5	SET5
1AMBW0006A	Wheel Bearing	Alfa Romeo 11900.21413.01; Alfa Romeo 60523334; Audi 009-311-219; Audi 010-409-607; Audi 211-405-625; Audi 211-405-625A; Audi 211-405-625X; Audi 211-405-645C; Audi 909-87-60-000; Austin-Western A25169A; BMW 2634106; BMW 31-21-1-468-890; BMW 31-21-1-634-106; BMW 31-21-2-634-106; British Leylands 142919; British Leylands 184399; British Leylands 524158; British Leylands BTC280; British Leylands C15351; British Leylands GHB105; British Leylands UKCO169; Bucyrus-Erie 26818010; Case G57204; Daihatsu 90368-31067-000; Dexter Axle K71-307-00; Eaton 550762; Euclid E551718; Daihatsu 90368-31067-000; Dexter Axle K71-307-00; Eaton 550762; Euclid E551718; Fiat 4096101; Ford 11407629; Ford 3913499; Ford 81AB-12388A; Ford 8A-1200C; Ford 8A-1201A; Ford C3HA-1200A; Ford C3HA-1200B; Ford C3XZ-1200A; Ford C3XZ-1200A1; Ford D5NN-1200A; Ford E02Z-7F431B; Ford E3TZ-1200A; Ford E0ZZ-7F431B; Ford F6RZ-71218A; Ford F6RZ-7F431A; Ford F6ZZ-71218A; Ford F6ZZ-71218B; Ford F6ZZ-7F431AA; GMC 12541277; GMC 12547209; GMC 457196; GMC 7413406; GMC 7450630; GMC E551718; Hyundai 52720-36200; International 3142103R91; International 594873R91; International 651819R91; International 652075R91; International 652081R91; International 828086R91; International F5K6146; Isuzu 8-00457196-0; Isuzu 8-97028116-0; Jaguar 8L03029; Jaguar C15351; John Deere AQX42845; John Deere JXD49008; Kenworth KW1772; Kewanee Machine X5628; Lee Norse 1025832; Massey-Ferguson 893373; Massey-Ferguson ET31127; Mazda 1243-33-047; Mazda 8501-33-075; Mazda ZLLO-33-075; Mazda ZLLO-33-075A; Mercedes-Benz 0009815805; Mercedes-Benz 0019810805K3; Mitsubishi MB002072; Mitsubishi MB515026; Mitsubishi MD717511; New Holland 136903; New Holland 218230; Nissan 38440-41B12; Nissan 40210-A0100; Nissan 40210-A0600; Opel 320018; Opel 328018; Opel N055110; Opel N055111; Porsche 999.059.001.00; Porsche 999.059.006.00; Porsche 999.059.012.00; Porsche 999.059.018.00; Porsche 999.059.098.00; Seat GE15823600; Toyota 90368-31002; Toyota 90368-31036; Toyota 90368-31036-85; Toyota 90368-31067; Triumph 142919; Twin Disc MA327; Vauxhall 8824111; Volvo 181589; VW 009-311-219; VW 010409607; VW 211-405-625; VW 211405625A; VW 211-405-625C; VW 211405645C; White 102720A; White 402239E5;	S6	A6			BR6	SET6
1AMB88107H	Wheel Bearing	A.E.C. (BMC) AE12; A.E.C. (BMC) AE14S; A.E.C. (BMC) AE15; Butler (Division Of 510088-1X; Butler (Division Of 510088-1X2; Butler (Division Of 510088-1XWF; Butler (Division Of 510090-1X; Butler (Division Of 510367-1XWF; Butler (Division Of 510370-1X; Checker 03568; Eaton MM6036; Eaton MM6037; Ford B9TZ-4800A; Ford D4TA-4800AA; Ford D4TJ-4800BA; Ford D4TZ-4800-A; Ford D4TZ-4800B; Ford D5UZ-4800-A; Ford D8TZ-4800-A; Ford D9TZ-4800A; Ford F2TA-4800AA; Ford F2TZ-4800A; Ford F5TZ-4800AA; Ford F5TZ-4800AA; Ford F81A-4800A; Ford F81A-4800BA; Ford F81Z-4800BA; Ford F81Z-4800CA; GMC 2343325; International 383-182-C91; International 386-418-C91; International 427349C91; International 432377C91; White 694297;		HB88107A		HB88107-A	HB88107A	
1AMB88508H	Wheel Bearing	A.E.C. (BMC) AE11; Butler (Division Of 510866-1X; Butler (Division Of 510873-1X; Butler (Division Of 511016-X; Butler (Division Of 511016-X3; Ford D4TA-4800AA; Ford D5TZ-4800-A; Ford E4TZ-4800A; GMC 12377850; GMC 12544546; GMC 15580345; GMC 15580347; GMC 719413; GMC 720161; GMC 790216; International 468-656-C91; International 468-666-C91; Rockwell CB211016X; Rockwell CB310003-1X;		HB88508A		HB88508-A	HB88508A	
1AMB104910	Wheel Bearing	Allis-Chalmers 0927272; Allis-Chalmers 4630857; Allis-Chalmers 70927272; Allis-Chalmers 709272728; Allis-Chalmers P12603E; BMW 33-131-206-453; BMW 33-131-469-966; BMW 33-133-206-453; British Leylands 571873; Bucyrus-Erie 26845350; Bucyrus-Erie 26845352; Caterpillar 953581; Clark SA39799; Eaton 127539; Eaton 312583; Eaton XET95789; Euclid 9432696; Ford 00400; Ford C9NN-7N041A; Ford C9NN-7N043A; Ford D3HZ-7169A; Ford D7TZ-1243A; FWD 93426; Galion D11497; GMC 00450; GMC 7455617; GMC 9432694; GMC 9432696; GMC 9437512; GMC 9440848; International 144077C1; International 144078C91; International 376463C1; International 376464C91; International 37E43019; International 533728R91; International 591652C1; International 591653C91; Jeffrey 69158; John Deere 39X21350A; John Deere 9X4374; John Deere JD9106; Joy 960301-1; Mack 64AX294; Massey-Ferguson 834999M1; Massey-Ferguson TXA44132; Porsche 999.059.056.00; Toyota 90080-36064; Toyota 90368-49084; Toyota 90368-49084-77; Toyota 90368-49085; Versatile 49379; Volvo 183429; Volvo 183430; Wabco VA4770; White 168213A; White 50A5772; White 981002; White XR11411;	S609	JLM104910		JLM104910	JLM104910	
1AMB104948	Wheel Bearing	Allis-Chalmers 0927269; Allis-Chalmers 70927269; Allis-Chalmers 709272694; Allis-Chalmers P12602E; British Leylands 571874; Bucyrus-Erie 26845351; Caterpillar 953582; Clark SA39800; Eaton 312582; Eaton XET95788; Euclid 9432695; Ford C9NN-7N042A; Ford D3HZ-7127B; FWD 93428; Galion D11498; GMC E67-45; International 144076C91; International 533729R91; International 591797C91; Jeffrey 69157; John Deere 39X21349A; John Deere 9X4373; John Deere JD9041; Joy 950301-1; Mack 62AX489; Massey-Ferguson 834998M1; Massey-Ferguson TXA44133; New Holland 199954; Versatile 49378; Volvo 183428; Wabco VA4773; White 168214A; White 981001; White XR11410;	JLM104948	JLM104948		JLM104948	JLM104948	
1AMB102910	Wheel Bearing	Allis-Chalmers 0927273; Allis-Chalmers 927273; British Leylands UKC7306; Caterpillar 7J8209; Eaton ET95835; Ford C9AZ-4222A; Ford D0AW-4222A; GMC 12350939; GMC 15637265; GMC 9436775; GMC 9436777; Hyundai 52701-44120; Hyundai 52710-44120; International 399934C1; International 399935C91; International 400988C1; International 400989C91; International 408007C1; International 408008C91; John Deere JD9133; Kia OK01A-33-047; Kia K6725-33-347; Mazda S231-33-047; Mitsubishi MB092749; Mitsubishi MB932726; Mitsubishi MD092749; Mitsubishi MD098749; New Process (OEM) 17270; Rover RTC3095; Toyota 90080-36067; Toyota 90368-45087; Toyota 90368-45087-77; Toyota 90368-45089;	LM102910	LM102910		LM102910	LM102910	
1AMB102949	Wheel Bearing	Allis-Chalmers 0927270; Caterpillar 7J8210; Eaton ET95834; Ford C9AZ-4221A; Ford D0AW-4221A; Ford D5AW-4221A/B; GMC 10033471; GMC 15637269; GMC 9436776; GMC 9440844; International 399933C91; International 400987C91; International 408006C91; John Deere JD9076; New Process (OEM) 17273;	LM102949	LM102949		LM102949	LM102949	

Aftermarket Part Number Cross Reference Guide

All-Makes Magneti Marelli Offered by Mopar

Product: Wheel Bearings and Hub Assemblies

For Reference Only. See Application Guide for Actual Vehicle Application and Selection of Correct Part for Vehicle



Magneti Marelli Part Number	Part Attribute (If it drastically affects comparative cost)	OE Part Number	AC Delco Part Number	MOOG Part Number	Raybestos Part Number	SKF Part Number	Timken Part Number
1AMB29710	Wheel Bearing	Alfa Romeo 101444; Alfa Romeo 60502705; Alfa Romeo 60502736; Allis-Chalmers 4255821; Allis-Chalmers 555360; Allis-Chalmers 634226; Allis-Chalmers 74255821; Allis-Chalmers AX64927; Allis-Chalmers P12605E; Audi 003-519-085; Audi 003-519-085A; Audi 003-519-085B; Audi 003-519-185; Audi 003-519-185A; Audi 003-519-185B; Audi 003-519-189; Audi 003-519-189A; Audi 014-409-123A; BMW 31531210929; British Leylands GHB112; Case H751370; Caterpillar 6L9773; Caterpillar K7L3715; Ford 11408219; Ford 408876; Ford C10W-4222A; Ford C10W-4222; Ford C1UW-4220A; Ford C1UW-4222A; Ford C3HN-4222; Ford C3HW-4222; Ford F65A-1217AA; Ford YL8Z-4221CA; GMC 7451880; GMC E67-43; Hyster T1976A1321; International 160557C91; International 3074093R91; International 478793R1; International 815212C1; International 815213C1; International 815801C91; John Deere 39X20196A; John Deere JD8271; Massey-Ferguson 834136M1; Mazda NA01-27-350; Mitsubishi MB001315; Mitsubishi MB109051; New Holland 121506; Nissan 40215-M5600; Rolls-Royce UG12176; Rolls-Royce UG13553; Saab 810528; Studebaker RB122; Towmotor A69560; Triumph 134589; Twin Disc M2618; Twin Disc MA5908T; Versatile 1995; VW 003-519-085; VW 003-519-085A; VW 003-519-085B; VW 003-519-185; VW 003-519-185A; VW 003-519-185B; VW 003-519-189; VW 003-519-189A; VW 014-409-123A; White 10X35983; White MT23011;	S348	LM29710		LM29710	LM29710
1AMB29749	Wheel Bearing	Alfa Romeo 101489; Alfa Romeo 60502704; Allis-Chalmers 555361; Allis-Chalmers 634227; Allis-Chalmers 73104226; Allis-Chalmers AX65082; Allis-Chalmers P12604E; Audi 003-519-187; Audi 003-519-187A; Case H747758; Caterpillar 6L9774; Clark 1313660; Ford 408875; Ford C10W-4221A; Ford C10W-4221; Ford C1UW-4221A; Ford C1UW-4221B; Ford C3HW-4221; Ford F65A-1216AA; Ford F65Z-1216AA; GMC 9427890; Hyster T1976A1319; International 160558C91; International 815216C91; International 815217C91; John Deere 39X20195A; John Deere JD8988; Massey-Ferguson 834125M1; Massey-Ferguson 834135M1; Towmotor A69285; Twin Disc MA585CH; Versatile 1996; VW 003-519-187; VW 003-519-187A; Wabco 38518; White 10X35984;		LM29749		LM29749	LM29749
1AMB300811	Wheel Bearing	Audi 096-323-981; Audi 113-517-185B; Audi 113-517-185C; Audi 113-517-185D; Audi 113517197B; Audi 113517197C; Audi 803-405-625; Mercedes-Benz 000 981 62 05; Mercedes-Benz 0009802002; Mercedes-Benz 0009804202; Mercedes-Benz 008 981 62 05; Mercedes-Benz 1155860635; Mercedes-Benz 1155860735; Mercedes-Benz 1155860835; Mercedes-Benz 1155861135; Mercedes-Benz 1233500068; Mercedes-Benz 1235860035; Nissan 40215-25600; Nissan 40215-50W00; Nissan 40215-D0100; Nissan 40217-25600; Suzuki 09625-41001; VW 096-323-981; VW 113-187-185B; VW 113-517-185B; VW 113-517-185C; VW 113517197B; VW 113517197C;		LM300811		LM300811	LM300811
1AMB300849	Wheel Bearing	Audi 113517195B; Audi 113517195C; Mitsubishi MD720623; Nissan 40216-25600; VW 113517195B; VW 113517195C;		LM300849		LM300849	LM300849
1AMB86610	Wheel Bearing	AAM 74007784; Allis-Chalmers 1160001; Allis-Chalmers 662413; Allis-Chalmers 71160001; Allis-Chalmers 711600015; Allis-Chalmers 930211; Audi 003-519-251; Audi 003-519-251A; Audi 003-519-251B; Audi 003-519-251C; Audi 003-519-251D; Audi 003-519-255; Audi 003-519-255C; BMW 33121204305; BMW 33-121-468-895; BMW 3604155; British Leylands 141329; British Leylands 515204; Caterpillar 310426; Clark 1302389; Daihatsu 90368-30022; Eaton 596954; Eaton 596955; Eaton ET95837; Euclid 9034500; Ford 11527876; Ford 11527878; Ford 11553182; Ford 1124-4K3288A; Ford 1L2Z-1202BA; Ford CODW-4616A; Ford C3HW-4616; Ford CODW-4615A; Ford CODW-4615B; Ford YL8Z-4621BA; FWD 93448; FWD 93449; Galion D73570; GMC 10033487; GMC 12569918; GMC 7451202; GMC 7451206; GMC 9034500; GMC 9297991; GMC 9417784; GMC 9417786; GMC 9436127; Honda 8-09417784-0; Hyster 156194; International 400982R91; International 400984R1; International 405152R91; International 405154R1; International 406521R1; International 406523R91; International 530740R91; International 530741R1; International 530742R91; International 530743R1; International 591825C1; International 610248C91; International 871242R1; Isuzu 8-09417784-0; Jeffrey 900077; John Deere 39X20012A; John Deere 39X20112A; John Deere JD8267; Joy 9601981; Kaiser-Frazer 945739; Kenworth KW1459; Massey-Ferguson 834581M1; Massey-Ferguson TX39283; Mazda NA01-27-220; Mazda Z2L1-27-222; Mercedes-Benz 0009803302; Mercedes-Benz 001 980 89 02; Mitsubishi 02070317; Mitsubishi A141041; Mitsubishi MB092150; Mitsubishi MB393472; New Holland 141296; Opel 9417784; Saab 09417784; Saab 834305; Saab 9417784; Studebaker 1549625; Towmotor A310426; Towmotor A311706; Toyota 90366-20025; Toyota 90366-90025; Toyota 90368-30002; Toyota 90368-30022; Toyota 90368-30022-85; Toyota 90368-30024; Toyota 90368-30038; Toyota 90368-30069; Toyota 90368-30070; Toyota 90368-30071; Toyota 90368-38022; Triumph 141329; Volvo 181302; Volvo 181302-1; Volvo 183468; Volvo 183512; Volvo 183839; Volvo 183839-0; VW 003-519-251; VW 003-519-251A; VW 003-519-251B; VW 003-519-251C; VW 003-519-251D; VW 003-519-255; VW 003-519-255C; Wabco VP4222; White 107511;		M86610		M86610	M86610
1AMB86649	Wheel Bearing	Allis-Chalmers 1160007; Allis-Chalmers 70927952; Allis-Chalmers 709279525; Allis-Chalmers 927952; Audi 003519253; Audi 003519253C; British Leylands 144812; Eaton 596956; Eaton ET95836; Ford 11527877; Ford 11553181; Ford 1L24-1201BA; Ford 1L2Z-1201BA; Ford CODW-4621A; Ford C3HW-4621; Galion D73569; GMC 5689474; GMC 7451205; Hyster 156195; International 400983R91; International 405153R91; International 406522R91; International 591826C91; International 610249C91; John Deere JD8979; Joy 9501981; Massey-Ferguson 834580M1; Massey-Ferguson TX39282; Mazda Z2L1-27-210; Mitsubishi 02070316; New Holland 141295; Saab 834304; Towmotor A310431; Toyota 90368-30024; Toyota 90368-30072; Volvo 183511; VW 003519253; VW 003519253C; Wabco VP4221; Wagner Tool & Machin 329600; White 107510;		M86649		M86649	M86649
1AMBW1561R	Wheel Bearing	Ford 5L3W-1225AA; Ford 5L3Z-1225AA; Ford E0TZ-1225A; Ford E1TZ-1225A; Ford E1UZ-1225A; Ford E5TZ-1225A; Ford F75Z-1225BA; GMC 09439561; GMC 7455734; GMC 88982517; GMC 9439561;		R1561TV		R1561-TV	#N/A
1AM513067R	Wheel Bearing	AAM 74008157; GMC 12479031; GMC 9442126; Isuzu 8-12479031-0; Saab 12479031;		RP513067		R59047	TRP59047
1AMBW5707R	Wheel Bearing	Ford 1L24-38A79-AA1L2; Ford 1L24-3A379AA; Ford 1L2Z-3A379AA; Ford 3W1W-1225AA; Ford 3W1Z-1225AA; Ford C7AW-1225A; Ford C7AZ-1225A; Ford E0AZ-1225A; Ford E3TZ-3C123B; Ford E3ZZ-7F431B; Ford ESSZ-1225A; Ford F57Z-3A379AB; GMC 12471606; GMC 3868746; GMC 7451405; GMC 7451595; GMC 7451785; GMC 9428573; Honda 8-07451785-0; Honda 8-09428573-0; Honda 8-97081945-2; Isuzu 8-07451785-0; Isuzu 8-09428573-0; Isuzu 8-97081945-2; Mazda 1F70-26-151; Mazda Z2L1-26-151; Nissan C2319-P9500; Warner Gear 1351-134-001;		RP5707		R1563	TPR1563TAV
1AMBW6408R	Wheel Bearing	Ford E3TW-1225AA; Ford E3TZ-1225A; Ford E3TZ-1225AA; GMC 15595140; GMC 7451275; GMC 7451809; GMC 88927028; GMC 94400097; GMC 94400097; John Deere JD8642; Mazda Z2L0-26-175; Mazda Z2L1-26-175; Mitsubishi 03507898AB; Mitsubishi 3507898AB;		RP6408		R1559	TPR1559RP
1AMBW001SB	Wheel Bearing	Ford E3TZ-3C076A;		SBK1		BK1	SBK1

Note: Part numbers and applications are subject to change without notice.7